

# BLACK EAGLE® ATHLETIC 2.0 VT

high / desert / Side zip  
Art. No. 330005

Microfiber/textile, breathable inner liner, leg height 8 inch, antistatic, sole 018  
**Available sizes US 4 – 13 & half sizes, Extra large sizes US 14 / 15 / 16**  
**Available widths: medium, wide**



330005



HAIX® 2-Zone Lacing



Sidezipper



#### Upper Material

Microfiber/textile combination

#### Inner Lining

Breathable inner liner

#### Insole

Comfortable, cushioning and moisture repellent. Separate heel shape for good cushioning and foot insertion. "AIRFLOW" channels.

#### Running sole

Made of rubber, resistant to fuel-oil, insulate against heat and cold, non-marking, self cleaning

#### Midsole

2-component PU, light, cushioning, supporting

#### Durable Sole

Rubber mixture for long durability.

#### Anti Slip

Excellent grip on a variety of terrains, even in the cold due to specific outsole design and use of special rubber.

#### HAIX® Climate System

The HAIX® Climate system uses the pumping movement, which permits air circulation with every step – moist air is released and fresh air comes in through the Micro-Dry lining/vent holes at the top of the boot.

#### HAIX® 2-Zone Lacing

Two Zone Lacing System enables a separate adjustment of the boot to the foot and leg area.

#### HAIX® Ankle Protector System

Safety Protection zones to prevent injury to the ankle.

#### Others

Low weight, pull strap, closed lacing system with lace pocket, toe bumper for additional abrasion protection, antistatic, sole is very non-skid in wet and cold conditions, durable, good cushioning effect, side zip.

#### Extended Wear Program

Out of warranty footwear can be refurbished with original factory parts through an extended wear package. This package includes any necessary replacement or repair of stitching, profiled rubber toe caps, insoles, and retreading of soles. Footwear will be cleaned and deodorized. HAIX footwear owners also have the option of a sole retread only or a toe cap replacement only.

|    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |     |    |     |    |     |    |     |    |     |    |
|----|----|----|----|----|----|----|----|----|----|----|----|----|----|-----|----|-----|----|-----|----|-----|----|-----|----|-----|----|
| UK | 3  | 3½ | 4  | 4½ | 5  | 5½ | 6  | 6½ | 7  | 7½ | 8  | 8½ | 9  | 9½  | 10 | 10½ | 11 | 11½ | 12 | 12½ | 13 | 13½ | 14 | 14½ | 15 |
| EU | 35 | 36 | 37 | 37 | 38 | 39 | 39 | 40 | 41 | 41 | 42 | 43 | 43 | 44  | 45 | 45  | 46 | 47  | 47 | 48  | 48 | 49  | 50 | 50  | 51 |
| US | 4  | 4½ | 5  | 5½ | 6  | 6½ | 7  | 7½ | 8  | 8½ | 9  | 9½ | 10 | 10½ | 11 | 11½ | 12 | 12½ | 13 | 13½ | 14 | 14½ | 15 | 15½ | 16 |

#### HAIX® North America Inc.

2320 Fortune Drive, Suite 120, Lexington, KY 40509  
Phone 859-281-0111, Fax 859-281-0113  
Toll free 866-344-HAIX (4249), [www.haix.com](http://www.haix.com)